



---

## Uploaded to VFC Website

▶▶▶ July 2013 ◀◀◀

---

This Document has been provided to you courtesy of Veterans-For-Change!

Feel free to pass to any veteran who might be able to use this information!

For thousands more files like this and hundreds of links to useful information, and hundreds of "Frequently Asked Questions, please go to:

[Veterans-For-Change](#)

---

*Veterans-For-Change is a 501(c)(3) Non-Profit Corporation  
Tax ID #27-3820181*

***If Veteran's don't help Veteran's, who will?***

We appreciate all donations to continue to provide information and services to Veterans and their families.

[https://www.paypal.com/cgi-bin/webscr?cmd=\\_s-xclick&hosted\\_button\\_id=WGT2M5UTB9A78](https://www.paypal.com/cgi-bin/webscr?cmd=_s-xclick&hosted_button_id=WGT2M5UTB9A78)

---

**Note:**

VFC is not liable for source information in this document, it is merely provided as a courtesy to our members.



ABSTRACT

To assess the environmental quality of White Sands Missile Range (WSMR) with regard to the use, storage, treatment, and disposal of toxic and hazardous materials and to define any condition which may adversely affect health and welfare or result in environmental degradation.

A review of the records indicated that the test ranges, burial sites, holding ponds, and demolition grounds represent the major contaminated areas.

Predominant contaminants include petroleum-oil-lubricants (POL), pesticides (DDT, chlordane, dieldrin, toxaphene, lindane, heptachlor, etc.), herbicides (2,4-D and 2,4,5-T), propellants, radioactive materials (depleted uranium), and explosive wastes.

WSMR covers over 1.8 million hectares (including the Co-use Area) and is situated in an enclosed basin. Most of the surface drainage flows toward the center of the range. The available geological evidence and water quality data do not indicate the offpost migration of contaminants via surface or subsurface waters.


No preliminary survey is recommended.



WS2/gen

**INSTALLATION ASSESSMENT  
OF  
WHITE SANDS MISSILE RANGE  
REPORT NO. 138**

**APRIL 1979**



**US ARMY  
TOXIC AND HAZARDOUS MATERIALS AGENCY**

**ABERDEEN PROVING GROUND, MARYLAND 21010**


DISTRIBUTION LIMITED TO US GOVERNMENT AGENCIES ONLY.  
FOR PROTECTION OF PRIVILEGED INFORMATION EVALUATING  
ANOTHER COMMAND: APRIL 1979. OTHER REQUESTS FOR  
THIS DOCUMENT MUST BE REFERRED TO: COMMANDER,  
WHITE SANDS MISSILE RANGE, WHITE SANDS, NEW MEXICO 88002.



WS2/gen

**INSTALLATION ASSESSMENT  
OF  
WHITE SANDS MISSILE RANGE  
REPORT NO. 138**

**APRIL 1979**



**US ARMY  
TOXIC AND HAZARDOUS MATERIALS AGENCY**

**ABERDEEN PROVING GROUND, MARYLAND 21010**

DISTRIBUTION LIMITED TO US GOVERNMENT AGENCIES ONLY.  
FOR PROTECTION OF PRIVILEGED INFORMATION EVALUATING  
ANOTHER COMMAND: APRIL 1979. OTHER REQUESTS FOR  
THIS DOCUMENT MUST BE REFERRED TO: COMMANDER,  
WHITE SANDS MISSILE RANGE, WHITE SANDS, NEW MEXICO 88002.



## ABSTRACT

To assess the environmental quality of White Sands Missile Range (WSMR) with regard to the use, storage, treatment, and disposal of toxic and hazardous materials and to define any condition which may adversely affect health and welfare or result in environmental degradation.

A review of the records indicated that the test ranges, burial sites, holding ponds, and demolition grounds represent the major contaminated areas.

Predominant contaminants include petroleum-oil-lubricants (POL), pesticides (DDT, chlordane, dieldrin, toxaphene, lindane, heptachlor, etc.), herbicides (2,4-D and 2,4,5-T), propellants, radioactive materials (depleted uranium), and explosive wastes.

WSMR covers over 1.8 million hectares (including the Co-use Area) and is situated in an enclosed basin. Most of the surface drainage flows toward the center of the range. The available geological evidence and water quality data do not indicate the offpost migration of contaminants via surface or subsurface waters.

No preliminary survey is recommended.